DAILY WORK ORDER					
	Work		od:		
Bossert Manufacturing	7/31	/87 			
Contractor: O. H. Materials Contractor Rep.: Paul Street	OSC:	Jack	D. Har	mon	
WORK PLANNED/AUTHORIZED:	WORK	ACCO	MPLISHE	D FROM	
1.)Continue to clean out sumps (Sumps #40, #37, & #36)	PREVIOUS WORK ORDER:				
2.)Continue to move MT bins		Yes	No	Continues	
from area #5 to area #6	1.)	(x)	()	()	:
3.)Laser area #16 and sumps #7 & #55	2.)	(×)	$\left(\right)$	()	
4.)Consolidate PCB and waste oil			$\left(\cdot \right)$		
drums into 12K PCB oil pool	4.)	()	$\left(\right)$	(X)	
	5.)	(x)	$\left(\cdot \right)$	()	
6.)Stage all vats in area #2	6.)	(X)	()	()	
	COMM	ENTS:	1977 WAS GOOD WOOD 1987 SHAP S	THE COLD STATE STATE SERVICES STATE	.
,					

Upp 1444 Mad 1445 444 1157 444 1157 1157 1157 1157 1					
EQUIPMENT PLANNED/AUTHORIZED: (3) Vans (2) Pick-up Truck (1) Decon trailer (3) Bobcats	EQUIPMENT USED FROM PREVIOUS DAY: -				
 Command Post Trailer Crew Trailer (3) 12K Pools 	All Authorized				
(1) Portable Eye Wash (1) Cars (6) Radioes (1) 50K Pool	COMMENTS:				
(1) Water Treatment System					
w/ appurtenances (2) High-Pressure Water Laser w/hoses (1) Mini-Trackhoe					
(20) Propane tanks (1) Hi-Lift					
(1) Cascade System (4) Porta-Johns (1) 955 Loader					
(1) 6-CY Dumpster (1) 3-in					
(4) Submersible Pumps: (3) 2-in (3) Satelites (2) 6.5KW Generators	427698 100%00 00500 00500 00500				
(1) Pneumatic Forklift	(182))) About they are a course to a cour				
PERSONNEL AUTHORIZED:	(1) Foreman (3)				
(1) Response Manager	(2) Foreman (2)				
AAAA OF COLL OD ACTIVITY TO SELECT	oberacor (5)				
Contractor Signature:	OSC Signature:				
Wester wy	Stad D. Han				
Date: 7/3/87	Date: 7/21/02				
(3) Satelites (2) 6.5KW Generators (1) Pneumatic Forklift PERSONNEL AUTHORIZED: (1) Response Manager (2) Laborer (1) Lab Technician (2) (10) Clean-up Technician (1) Contractor Signature:	(2) Foreman (2) (1) Field Clerk (4) Clean-up Technician (2) (1) Operator (2) OSC Signature:				